

Huawei H31-411

Huawei Certified ICT Associate-LTE

For More Information – Visit link below:

<https://www.examsempire.com/>

Product Version

- 1. Up to Date products, reliable and verified.**
- 2. Questions and Answers in PDF Format.**



<https://examsempire.com/>

Visit us at: <https://www.examsempire.com/h31-411>

Latest Version: 6.0

Question: 1

Which actions are recommended if commissioning does not complete successfully?
(Select all that apply)

- A. Review commissioning logs
- B. Verify configuration data
- C. Ignore minor alarms
- D. Check hardware and transmission status
- E. Restart the commissioning process

Answer: A,B,D,E

Question: 2

What is a key consideration when designing a high-speed railway LTE site solution?

- A. User billing models
- B. Handover performance
- C. Core network redundancy
- D. License activation timing

Answer: B

Question: 3

Which activity is typically performed after successful commissioning?

- A. Site acceptance testing
- B. Hardware replacement
- C. License deactivation
- D. Power shutdown

Answer: A

Question: 4

Which conditions must be met before performing remote commissioning?
(Select all that apply)

- A. Transmission link is available
- B. Hardware installation is complete
- C. EPC configuration is finalized
- D. Power supply is stable
- E. RF optimization is finished

Answer: A,B,D

Question: 5

What is the primary objective of MBTS GUL software commissioning?

- A. Optimizing LTE KPIs
- B. Making the base station operational
- C. Expanding network capacity
- D. Replacing faulty hardware

Answer: B

Question: 6

After completing hardware replacement, which action should be performed next?

- A. Leave the site immediately
- B. Shut down the base station
- C. Verify system status and alarms
- D. Start KPI optimization

Answer: C

Question: 7

What is the primary role of an eNodeB in LTE?

- A. Radio access and scheduling
- B. Core network switching
- C. Subscriber authentication
- D. Charging management

Answer: A

Question: 8

Which checks are typically included in MBTS radio layer maintenance?
(Select all that apply)

- A. Verifying RF unit status
- B. Inspecting antenna and feeder connections
- C. Confirming power output levels
- D. Checking VSWR and signal quality
- E. Modifying EPC subscriber profiles

Answer: A,B,C,D

Question: 9

During MBTS GUL field maintenance, which action should be performed first when a critical hardware alarm is reported on U2020?

- A. Replace the suspected board immediately
- B. Power off the entire base station
- C. Analyze alarm details and confirm the fault location
- D. Reboot the eNodeB remotely

Answer: C

Question: 10

When preparing initial configuration data, which factor is most critical to verify?

- A. User service plans
- B. Billing system status
- C. Historical KPI trends
- D. Consistency with network planning

Answer: D

Thank You for Trying Our Product
Special 16 USD Discount Coupon: NSZUBG3X

Email: support@examsempire.com

**Check our Customer Testimonials and ratings
available on every product page.**

Visit our website.

<https://examsempire.com/>